



City of Portland
 Chain-of-Custody
 Bureau of Environmental Services



Date: 9/16/08
 Page: 1 of 1
 Collected By: SB Thom
 Parks

Project Name: **PARKS TURF SAMP**

Project Manager: Taryn Meyer

BES-Project #:

File Number: 3030.196

Wipe samples taken from Reike and Delta Park turf playing fields.

Desired Turn-Around: Standard PUSH ASAP

Sample I.D. (W/PCL Use Only)	Location	Sample Date	Sample Time	Sample Type	Soil / Water	General	Requested Analyses	Metals	Additional Information
LAB 081204	Reike	9/16/08	1530	wipe	G				
LAB 081205	Reike grass		1535	Solid	G				
LAB 081206	Reike Blank		1540	wipe	G				
LAB 081207	Delta Park Old		1430	wipe	G				
LAB 081208	Delta Park grass		1435	Solid	G				
LAB 081209	Delta Park Blank		1450	wipe	G				
LAB 081210	Delta Park New		1500	wipe	G				
LAB 081211	Delta Park newgrass		1510	Solid	G				
	Delta Park Blank		1515						

COMMENTS:

Samples delivered by courier

Relinquished By: 1. Signature: <u>Suzanne H. Meyer</u> Printed Name: <u>Suzanne H. Meyer</u> Date: <u>9/16/08</u> Time: <u>1600</u>	Relinquished By: 2. Signature: _____ Printed Name: _____ Date: _____ Time: _____	Relinquished By: 3. Signature: _____ Printed Name: _____ Date: _____ Time: _____	Relinquished By: 4. Signature: _____ Printed Name: _____ Date: _____ Time: _____
Received By: _____ Signature: _____ Printed Name: _____ Date: _____ Time: _____	Received By: 2. Signature: _____ Printed Name: _____ Date: _____ Time: _____	Received By: 3. Signature: _____ Printed Name: _____ Date: _____ Time: _____	Received By: 4. Signature: _____ Printed Name: _____ Date: _____ Time: _____

Printed Name: Karen Wagner Date: 9/16/08

s:\eid\3030.xxx\sample\parks Turf Samp COC (9-16-08).xls

9/16/2008



City of Portland
Water Pollution Control Laboratory
6543 N. Burlington Ave. / Portland OR 97203 (503) 823-5600 fax (503) 823-5656



LABORATORY ANALYSIS REPORT

Sample ID: **LAB081210**

Sample Collected: 09/16/08 15:00
Sample Received: 09/16/08

Sample Status: COMPLETE AND
VALIDATED

Proj./Company Name: PARKS TURF SAMP
Address/Location: DELTA PARK NEW

Report Page: Page 1 of 1

Sample Point Code: 0
Sample Type: GRAB
Sample Matrix: OTHER

System ID: AM08628
EID File #: 3030.196
LocCode: PARKSTUR
Collected By: SB/THM

Comments:

QA/QC: Unless otherwise noted, all analytical QA/QC criteria were met for this sample including holding times, calibration, method blanks, laboratory control sample recoveries, duplicate precision, matrix spike recoveries, and surrogate recoveries, as applicable.

Test Parameter	Result	Units	MRL	Method	Analysis Date
METALS LEAD	0.473	µg/wipe	0.2	EPA 6010	09/17/08

End of Report for Sample ID: LAB081210

New turf is installed by Playersturf USA.

*Playersturf USA
6107 SW Murray Blvd. #437
Beaverton, OR 97008
Phone: (503) 544-9966*

Report Date: 09/23/08

Validated By: 



City of Portland
Water Pollution Control Laboratory
6543 N. Burlington Ave. / Portland OR 97203 (503) 823-5600 fax (503) 823-5656



LABORATORY ANALYSIS REPORT

Sample ID: **LAB081211**

Sample Collected: 09/16/08 15:10
Sample Received: 09/16/08

Sample Status: COMPLETE AND
VALIDATED

Proj./Company Name: PARKS TURF SAMP
Address/Location: DELTA PARK NEW GRASS

Report Page: Page 1 of 1

Sample Point Code: 0
Sample Type: GRAB
Sample Matrix: OTHER

System ID: AM08629
EID File #: 3030.196
LocCode: PARKSTUR
Collected By: SB/THM

Comments:

QA/QC: Unless otherwise noted, all analytical QA/QC criteria were met for this sample including holding times, calibration, method blanks, laboratory control sample recoveries, duplicate precision, matrix spike recoveries, and surrogate recoveries, as applicable.

Test Parameter	Result	Units	MRL	Method	Analysis Date
METALS LEAD	<0.500	mg/Kg dry wt	0.5	EPA 6010	09/17/08

End of Report for Sample ID: LAB081211

Report Date: 09/23/08

Validated By: